

Number of Notices of Violation and Odor Complaints - Sunshine Canyon Landfill




Date)

of NOV

Number of Notices of Violation and Odor Complaints - Sunshine Canyon Landfill



Number of Notices of Violation and Odor Complaints - Sunshine Canyon Landfill



- 1. Due to rain, stormwater spilled onto SF Road; Drilling of 15 vertical gas wells;
- 2. Continue drilling of 15 vertical gas wells: Condensate leaked from well 813 during installation of well pump.
- 3. Landfill rec'd trash starting from 9:00 AM; a subsurface liquid line near main haul was damage causing 3,000 gals spille on main haul road and some entered into strom drain channel.
- 4. As of 04/24, 100 new vertical gas wells were installed and pumps are being installed to address liquids.
- 5. 05/14 Gas header line leaked 200 gals discharged onto main haul road and some entered into storm drain channel and Terminal Basin
- 6. 06/08 a slide occurred on the western edge of the CC-4 Part 2 subgrade excavation.
- 06/22 500 gals leak from a blind flange on leachate line.

- 7. 07/18 Leak from a blind flange on leachate line caused 200 gals release into trench at toe of CC-3B and onto main haul road.
- 8. 08/16 Repair work for the landslide that occured on 06/08 was completed.
- 08/24 LEA issued a violation for gas and monitoring control (probe registered an exceedance of over
- -08/24 A force main line was struck by a scraper near CC-4 Part 1, causing a1,500 gals of liquid discharged.
- 08/25 A pipe ruptured causing 600 gals of dust control water to discharge into the concrete lined channel and entered the TB but contained in TB and was pumped out.


- 9. 9/25 Leak from a blind flange on a force main line at the toe of cell CC-3A caused a 200 gals discharge.
- **10.** 11/2 Fernco boot on CGW-2133 dislodged off well casing causing 300 gals of liquid to release.
- -11/14 Clogged pumps at the toe of cell CC-3B caused 100 gals of liquid discharg. -11/29 Clogged pumps at the toe of cell CC-3B caused 500 gals of liquid discharge.
- **11.** 12/1, 2, 11, 12,13 liquid seeping on the customer haul road at toe of Cell CC-4 Part
- -12/6 100 gals of liquid spilled from broken wellhead CGW2152.
- -12/6 800 gals of liquid from the leachate tank farm spilled into containment area.

- 12. 1/9 ATC 27 and CGW2133 well heads dislodged causing 10 gals and 100 gals of liquid to spill
- 1/30 GW1035D wellhead dislodged causing 200 gals of leachate spill.
- 1/31 100 gals of condensate spilled from pipe near CC-3A.
- 13. 2/18 Fernco connection on GW918 popped off spilling 100 gal 17. 06/12 100 gals spilled from of liquid.
- 14. 3/12 Fernco connection on GW3020 popped off and spilled 100 gals of liquid.
- -3/23 GW 3010 spilled 500 gals of liquid during routine maintenance on pump.

- 15. 04/05 AHW10 (Closure Turf Area) dislodged causing 100 gals to spill.
- 04/19 CGW2046 (near Flare Station) dislodged 200 gals.
- 16. 05/07 20k gals of groundwater spilled into the terminal basin. Spill was contained in TB, no liquids were discharged from site. LEA and Water Board were notified.
- sample line at lower treatment facility.
- 18. 07/18 To mitigate potential spills, Republic in process of converting all Fernco wellhead connections to hardpipe connections on wells w/pumps in CC-3A.

- Note: 1.) Number of complaints are based on AQMD's Complaint Summary Monthly Reports.
 - 2.) Number of Notices of Violation are based on SCAQMD's Facility Information Detail (FIND) website.
 - 3.) Schools nearby are usually off in early June and resume around 2nd week of August.
 - 4.) Leachate collected is based on Republic Services' Summary of Water Sources Quarterly Reports to the SCL LEA.

Surface Gas Emissions and Number of Odor Complaints - Sunshine Canyon Landfill




^{2.)} Number of Notices of Violation are based on SCAQMD's Facility Information Detail (FIND) website.

^{3.)} Schools nearby are usually off in early June and resume around 2nd week of August.

^{4.)} Leachate collected is based on Republic Services' Summary of Water Sources Quarterly Reports to the SCL.


Surface Gas Emissions and Number of Odor Complaints - Sunshine Canyon Landfill



Surface Gas Emissions and Number of Odor Complaints - Sunshine Canyon Landfill







- **1.** Due to rain, stormwater spilled onto SF Road; Drilling of 15 vertical gas wells;
- 2. Continue drilling of 15 vertical gas wells; Condensate leaked from well 813 during installation of well pump.
- 3. Landfill rec'd trash starting from 9:00 AM; a subsurface liquid line near main haul was damage causing 3,000 gals spille on main haul road and some entered into strom drain channel.
- **4.** As of 04/24, 100 new vertical gas wells were installed and pumps are being installed to address liquids.
- 5. 05/14 Gas header line leaked 200 gals discharged onto main haul road and some entered into storm drain channel and Terminal Basin (TB).
- **6.** 06/08 a slide occurred on the western edge of the CC-4 Part 2 subgrade excavation.
- 06/22 500 gals leak from a blind flange on leachate line.

- 7. 07/18 Leak from a blind flange on leachate line caused 200 gals release into trench at toe of CC-3B and onto main haul road.
- **8.** 08/16 Repair work for the landslide that occured on 06/08 was completed.
- 08/24 LEA issued a violation for gas and monitoring control (probe registered an exceedance of over 5%)
- 08/24 A force main line was struck by a scraper near CC-4 Part 1, causing a1,500 gals of liquid discharged.
- 08/25 A pipe ruptured causing 600 gals of dust control water to discharge into the concrete lined channel and entered the TB but contained in TB and was pumped out.


- **9.** 9/25 Leak from a blind flange on a force main line at the toe of cell CC-3A caused a 200 gals discharge.
- **10.** 11/2 Fernco boot on CGW-2133 dislodged off well casing causing 300 gals of liquid to release.
- -11/14 Clogged pumps at the toe of cell CC-3B caused 100 gals of liquid discharg. -11/29 Clogged pumps at the toe of cell CC-3B caused 500 gals of liquid discharge.
- **11.** 12/1, 2, 11, 12,13 liquid seeping on the customer haul road at toe of Cell CC-4 Part
- -12/6 100 gals of liquid spilled from broken wellhead CGW2152.
- -12/6 800 gals of liquid from the leachate tank farm spilled into containment area.

- **12.** 1/9 ATC 27 and CGW2133 well heads dislodged causing 10 gals and 100 gals of liquid to spill.
- 1/30 GW1035D wellhead dislodged causing 200 gals of leachate spill.
- 1/31 100 gals of condensate spilled from pipe near CC-3A.
- **13.** 2/18 Fernco connection on GW918 popped off spilling 100 gal of liquid.
- **14.** 3/12 Fernco connection on GW3020 popped off and spilled 100 gals of liquid.
- -3/23 GW 3010 spilled 500 gals of liquid during routine maintenance on pump.

- **15.** 04/05 AHW10 (Closure Turf Area) dislodged causing 100 gals to spill.
- 04/19 CGW2046 (near Flare Station) dislodged 200 gals.
- **16.** 05/07 20k gals of groundwater spilled into the terminal basin. Spill was contained in TB, no liquids were discharged from site. LEA and Water Board were notified.
- **17.** 06/12 100 gals spilled from sample line at lower treatment facility.
- **18.** 07/18 To mitigate potential spills, Republic in process of converting all Fernco wellhead connections to hard-pipe connections on wells w/pumps in CC-3A.

- Note: 1.) Number of complaints are based on AQMD's Complaint Summary Monthly Reports.
 - 2.) Number of Notices of Violation are based on SCAQMD's Facility Information Detail (FIND) website.
 - 3.) Schools nearby are usually off in early June and resume around 2nd week of August.
 - 4.) Leachate collected is based on Republic Services' Summary of Water Sources Quarterly Reports to the SCL LEA

Leachate Collected and Number of Odor Complaints - Sunshine Canyon Landfill




^{2.)} Number of Notices of Violation are based on SCAQMD's Facility Information Detail (FIND) website.


^{3.)} Schools nearby are usually off in early June and resume around 2nd week of August.

^{4.)} Leachate collected is based on Republic Services' Summary of Water Sources Quarterly Reports to the SCL.

Leachate Collected and Number of Odor Complaints - Sunshine Canyon Landfill



Leachate Collected and Number of Odor Complaints - Sunshine Canyon Landfill



- 1. Due to rain, stormwater spilled onto SF Road; Drilling of 15 vertical gas wells;
- 2. Continue drilling of 15 vertical gas wells: Condensate leaked from well 813 during installation of well pump.
- 3. Landfill rec'd trash starting from 9:00 AM; a subsurface liquid line near main haul was damage causing 3,000 gals spille on main haul road and some entered into strom drain channel.
- 4. As of 04/24, 100 new vertical gas wells were installed and pumps are being installed to address liquids.
- 5. 05/14 Gas header line leaked 200 gals discharged onto main haul road and some entered into storm drain channel and Terminal Basin (TB).
- 6. 06/08 a slide occurred on the western edge of the CC-4 Part 2 subgrade excavation.
- 06/22 500 gals leak from a blind flange on leachate line.

- 7. 07/18 Leak from a blind flange on leachate line caused 200 gals release into trench at toe of CC-3B and onto main haul road.
- 8. 08/16 Repair work for the landslide that occured on 06/08 was completed.
- 08/24 LEA issued a violation for gas and monitoring control (probe registered an exceedance of over 5%)
- 08/24 A force main line was struck by a scraper near CC-4 Part 1, causing a1,500 gals of liquid discharged.
- 08/25 A pipe ruptured causing 600 gals of dust control water to discharge into the concrete lined channel and entered the TB but contained in TB and was pumped out.

- 9. 9/25 Leak from a blind flange on a force main line at the toe of cell CC-3A caused a 200 gals discharge.
- 10. 11/2 Fernco boot on CGW-2133 dislodged off well casing causing 300 gals of liquid to release.
- -11/14 Clogged pumps at the toe of cell CC-3B caused 100 gals of liquid discharg.
- -11/29 Clogged pumps at the toe of cell CC-3B caused 500 gals of liquid discharge.
- 11. 12/1, 2, 11, 12,13 liquid seeping on the customer haul road at toe of Cell CC-4 Part
- -12/6 100 gals of liquid spilled from broken wellhead CGW2152.
- -12/6 800 gals of liquid from the leachate tank farm spilled into containment area.

- 12. 1/9 ATC 27 and CGW2133 well heads dislodged causing 10 gals and 100 gals of liquid to spill.
- 1/30 GW1035D wellhead dislodged causing 200 gals of leachate spill.
- 1/31 100 gals of condensate spilled from pipe near CC-3A.
- 13. 2/18 Fernco connection on GW918 popped off spilling 100 gal 17. 06/12 100 gals spilled from of liquid.
- 14. 3/12 Fernco connection on GW3020 popped off and spilled 100 gals of liquid.
- liquid during routine maintenance CC-3A. on pump.

- **15.** 04/05 AHW10 (Closure Turf Area) dislodged causing 100 gals to spill.
- 04/19 CGW2046 (near Flare Station) dislodged 200 gals.
- 16. 05/07 20k gals of groundwater spilled into the terminal basin. Spill was contained in TB, no liquids were discharged from site, LEA and Water Board were notified.
- sample line at lower treatment facility.
- 18. 07/18 To mitigate potential spills, Republic in process of converting all Fernco wellhead connections to hard--3/23 GW 3010 spilled 500 gals of pipe connections on wells w/pumps in

Note: 1.) Number of complaints are based on AQMD's Complaint Summary Monthly Reports.

- 2.) Number of Notices of Violation are based on SCAQMD's Facility Information Detail (FIND) website.
- 3.) Schools nearby are usually off in early June and resume around 2nd week of August.
- 4.) Leachate collected is based on Republic Services' Summary of Water Sources Quarterly Reports to the SCL.